

FSN & FSCA Ref: 2020FA0001

Date: 14Jan2020

### Urgent Field Safety Notice

# Zenith Alpha<sup>™</sup> Spiral-Z<sup>®</sup> Endovascular Leg

For Attention of: Chief Executive / Risk Management / Purchasing

Contact details of local representative (name, e-mail, telephone, address etc.)

Cook Medical Europe Ltd. O'Halloran Road National Technology Park Limerick, Ireland E-mail: <u>European.FieldAction@CookMedical.com</u> Phone: Please refer to the attached Country Contacts List

For any further information or support concerning the information within this FSN please contact your local Cook Medical Sales Representative or Cook Medical Europe Ltd.



FSN & FSCA Ref: 2020FA0001

### Urgent Field Safety Notice (FSN)

# Zenith Alpha<sup>™</sup> Spiral-Z<sup>®</sup> Endovascular Leg

### Risk addressed by FSN

Information on Affected Devices							
1.	1. Device Type(s)						
1.	The Zenith Alpha <sup>™</sup> Spiral-Z <sup>®</sup> Endovascular Leg is part of a modular system consisting of multiple components, most typically a bifurcated main body and two iliac legs. The iliac legs are constructed of woven polyester fabric sewn to five self-expanding nitinol Cook-Z <sup>®</sup> stents and a continuous nitinol spiral stent with braided polyester and monofilament polypropylene suture. 2. Commercial name(s)						
١.	Zenith Alpha™ Spi		vascular Leg				
1.							
1.	3. Primary clinical purpose of device(s) Indicated for use with the Zenith Alpha Abdominal Endovascular Graft, Zenith Low Profile AAA/Zenith Alpha Abdominal Ancillary Components, Zenith Flex AAA Endovascular Graft, Zenith Renu AAA Ancillary Graft, Zenith Flex AUI Endovascular Graft, Zenith Fenestrated AAA Endovascular Graft, Zenith Branch Endovascular Graft-Iliac Bifurcation, and Zenith AAA Ancillary Components, during either a primary or a secondary procedure in patients who have adequate iliac/femoral access compatible with the required introduction systems. The graft is used in combination with these products for the endovascular treatment of abdominal aortic and aorto-iliac aneurysms.						
1.			gue/part number(		•		
	Reference Part Number (RPN)	Order Number	Reference Part Number (RPN)	Order Number	Reference Part Number (RPN)	Order Number	
	ZISL-9-42	G35955	ZISL-9-59	G35956	ZISL-9-77	G35957	
	ZISL-9-93	G34508	ZISL-9-110	G35959	ZISL-9-125	G35960	
	ZISL-11-42	G35961	ZISL-11-59	G35962	ZISL-11-77	G35963	
	ZISL-11-93	G35964	ZISL-11-110	G35965	ZISL-11-125	G35966	
	ZISL-13-42	G35967	ZISL-13-59	G35968	ZISL-13-77	G35969	
	ZISL-13-93	G35970	ZISL-13-110	G34409	ZISL-13-125	G34410	
	ZISL-16-42	G35971	ZISL-16-59	G35972	ZISL-16-77	G35973	
	ZISL-16-93	G35975	ZISL-20-42	G35977	ZISL-20-59	G35976	
	ZISL-20-77	G35980	ZISL-20-93	G35981	ZISL-24-42	G35982	
	ZISL-24-59	G35983	ZISL-24-77	G35984	ZISL-24-93	G35985	
1.	5. Affected s All lot numbers	serial or lot r	number range				



#### FSN & FSCA Ref: 2020FA0001

	Rea	ason for Field S	afety Correctiv	ve Action (FSCA	A)
2.	1. Description of the product problem				
	None				
2.	2. Hazard giving rise to the FSCA				
2.	This notice is to call customers attention to several aspects of the Instructions for Use (IFU) for the Zenith Alpha <sup>™</sup> Spiral-Z <sup>®</sup> Endovascular Leg that are of key importance when selecting and implanting a device. This notice is for information purposes only. No devices need to be returned, and patients already treated with this device should be followed in accordance with the current IFU. Investigation of thrombus formation and/or lumen occlusion reports for Zenith Alpha <sup>™</sup> Spiral-Z <sup>®</sup> Endovascular Legs identified that the factors listed in the table below have contributed to these failures. Therefore, Cook Medical is submitting this notification to all customers to highlight key points of the IFU pertaining to prevention of the identified contributing factors. In addition, the Planning and Sizing Worksheet has been updated to include information associated with the identified points from the IFU. A copy of the updated Planning and Sizing Worksheet is attached to this notice.				
	IFU INDICATIONS	CONTRIB		FOR THROMBUS	FORMATION
		1. Compression of	2. Misalignment of	3. Excessive	4. Compression of
		the flare on the ipsilateral leg within the main body gate	the ipsilateral and contralateral legs	overlap of the leg(s) above the main body graft bifurcation	the graft(s) within a narrowed / stenosed aortic bifurcation or iliac region
	20 mm 40 mm	55 mm			< 20 mm
2.	4. Predicted risl	k to patient			
۲.		•	llowed, graft comp	ression and fabric	infolding can occur,
	If the instructions listed below are not followed, graft compression and fabric infolding can occur, increasing the risk of a thromboembolic event and/or total occlusion of the leg graft.				



#### FSN & FSCA Ref: 2020FA0001

-			
2.	5. Further information to help characterise the problem		
	Key Points from the IFU Pertinent to Complaint Reports		
	Leg Placement		
	<ul> <li>When a 42mm or 59mm leg graft is used on the ipsilateral side, contralateral leg overlap into the contralateral main body limb should be limited to 16mm. Failure to do so may result in occlusion of the ipsilateral limb (Section 4.1).</li> <li>Closely align the proximal edge of the ipsilateral leg graft with the proximal edge of the previously placed contralateral leg graft (Section 10.1.5.4).</li> <li>Excessive overlap of 12mm above the main body graft bifurcation may increase the risk of limb thrombosis (Section 4.5).</li> </ul>		
	<ul> <li>Anatomical Measurements         <ul> <li>Pre-existing regions of stenosis/narrowing (less than approximately 20mm ID in the aorta or 7mm to 8mm ID in the iliacs) have been shown to increase the risk of a thromboembolic event (e.g., graft limb occlusion). Dilation of these regions with a noncompliant balloon and/or stent placement may be necessary to help assure maintained graft patency and to reduce the risk of a thromboembolic event (Section 4.2).</li> </ul> </li> </ul>		
2.	6. Background on Issue		
	Investigation of thrombus formation and/or lumen occlusion reports for Zenith Alpha <sup>™</sup> Spiral-Z <sup>®</sup> Endovascular Legs identified the factors above that contributed to these failures.		

# Type of Action to mitigate the risk

3.	1.	Action To Be Taken by the User		
		oxtimes Take note of reinforcement of Instructions For Use (IFU)		
3.	2.	Particular considerations for: Implantable devic	e	
		Is follow-up of patients or review of patients' previous results recommended? No		
		Patients already treated with this device should be followed in	n accordance with the current IFU.	
3.		Is customer Reply Required? rm is attached specifying deadline for return	Yes	

General Information			
4.	1. FSN Type	New	
4.	2. Further advice or information already expected in follow-up FSN?	No	
4.	3. Manufacturer information (For contact details of local representative refer to page 1 of this FSN)		
	a. Company Name	William Cook Europe	
	b. Address	Sandet 6 4632 Bjaeverskov Denmark	



#### FSN & FSCA Ref: 2020FA0001

4.	4. The Competent (Regulatory) Authority of your country has been informed about this communication to customers.		
4.	5. List of attachments/append ices:	Reply form Planning and Sizing work sheet Country Contacts List	
4.	6. Name/Signature	XXX	

Transmission of this Field Safety Notice				
This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred. (As appropriate)				
Please transfer this notice to other organisations on which this action has an impact. (As appropriate)				
Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action.				
Pleasereport all device-related incidentsto the manufacturer, distributor or local representative, and the national Competent Authority if acoropriate, as this provides important feedback.				