1785 Cressier FR / Switzerlan Phone: +41 (0)26 674 51 11 Fax: +41 (0)26 674 54 45

Cressier, 24 February 2021

Field Safety Notice / FSCA 001-21

Affected products displaying the issue:

Product Name	ld-n	Catalog No	Lot No	Expiry Date
DiaClon Anti- M/N*	51210	006011	51210 10 01	04.2021
			51210 11 01	06.2021
			51210 12 01	09.2021
			51210 12 02	10.2021
			51210 13 02	10.2021
DiaClon Anti-N	50221	007111	50221 05 01	04.2021
			50221 06 01	06.2021
			50221 07 01	07.2021
			50221 07 02	09.2021

^{*}The only impacted well of the card is the anti-N. There is no issue with anti-M and ctl well.

Dear Customer,

This letter contains important information that requires your immediate and urgent attention. Bio-Rad is voluntarily conducting a Field Safety Corrective Action for the products identified above.

Description of the problem:

We would like to share information about unexpected reactions that could be observed when using the DiaClon anti-N and DiaClon anti-M/N mentioned above.

Following customer feedback, we confirm that non-specific reactions could be observed in the **anti-N well (MNS2)** of the above-mentioned cards with N negative samples (MNS: -2).

The table 1 shows the range of false positive reactions that may occur.





Phone: +41 (0)26 674 51 11 Fax: +41 (0)26 674 54 45




Table 1: Example of non-specific reactions obtained on IH-500 with the impacted lots of card

The phenomenon is observed frequently when the ID-Cards are used on the IH-500. It is more rarely observed when the ID-Cards are used on IH-1000 or tested in the manual or semi-automated methods (Saxo ID-Reader II, Banjo ID-Reader, Swing TwinSampler, Classic ID-Gelstation).

Impact on the patient:

Impact on the result	There is a risk of a false positive result (up to 2+ maximum) for the typing of the N antigen when carried out with lot numbers listed above.
Risk in the context of donor typing	None as N positive blood units will not be used for transfusing a patient having a clinically significant anti-N
Risk in the context of patient typing	Delayed result - this antigen typing would be carried out for a patient presenting with a clinically significant anti-N. This inconsistency would lead to further testing.

We advise you to assess this situation with your biologist to determine if retesting is deemed necessary and take the appropriate course of action depending on the patient's clinical conditions, medical history, and other relevant laboratory data.



1785 Cressier FR / Switzerlan Phone: +41 (0)26 674 51 11 Fax: +41 (0)26 674 54 45

Immediate protective measure for the user:

Testing Method	Recommendation		
IH-500	1) Stop using the impacted ID-cards on the IH-500. 2) Use one of the following methods: • Manual method or, • semi-automated method or, • fully automated method with the IH-1000 analyzer, according to recommendations described below.		
IH-1000 and semi-automated methods	Deactivate the automatic validation of the results in IH-Com In case of a reaction shown as +/-, + or ++ by the instrument please follow the recommendations below: 1) Invalidate the result, 2) Repeat the test with the manual method		
Manual Method	If visual interpretation of the reaction is +/-, +, or ++ (refer to table 2): 1) Invalidate the result, 2) Repeat the test If retesting does not permit to conclude the presence or absence of the N antigen, use an alternative method such as an antigen profile determination including an incubation step at room temperature.		

Any negative reaction obtained with the impacted lots should be considered as valid and indicates the absence of the corresponding antigen.

Any positive reaction obtained with the impacted lots showing a reaction strength of +++ to ++++ (refer to table 2 or instrument interpretation) should be considered as valid and indicates the presence of the corresponding antigen.



DiaMed GmbH Pra Rond 23 1785 Cressier FR / Switzerland Phone: +41 (0)26 674 51 11

Fax: +41 (0)26 674 54 45




Table 2: Reading charter for visual interpretation of reaction strength

We request you transfer this information to all persons impacted in your institution and/or forward it to all locations where products may have been transferred.

Please note that the relevant European Regulatory Agency has been advised of this Field Safety Corrective Action.

In case of any questions, in the first instance, please contact your local technical support:

[insert local contact information/e-mail address]

Our representatives are briefed to help you manage this situation.

We apologize for any inconvenience that may have been caused by this action and we appreciate your prompt cooperation in this matter.

Yours sincerely,
