

March 04, 2022

To: Hospitals and Surgeons

Subject: URGENT MEDICAL DEVICE FIELD SAFETY NOTICE (REMOVAL)

Affected Product: Upper Trauma, Lower Trauma, Foot & Ankle and Sports Medicine

See Attachment 2 - Affected Product List

Biomet Orthopedic LLC is conducting a lot specific medical device Field Safety Corrective Action (removal) for various implants used in Upper Trauma, Lower Trauma, Foot & Ankle and Sports Medicine surgical procedures. Internal testing indicated that the packaging seal may not have sufficient adhesion on all sides of the pouch, which could potentially lead to a compromised sterile barrier and the risks identified below. The issue has been identified internally and so far, Zimmer Biomet did not receive complaints related to the issue.

| Risks | | | |
|--|---------------|--|--|
| Describe immediate health | Most Probable | Highest Severity | |
| consequences (injuries or illness) that may result from use of or exposure to the product issue. | None | A non-clinically significant extension of surgery to find another part readily available | |
| Describe long range health | Most Probable | Highest Severity | |
| consequences (injuries or illness) that may result from use of or exposure to the product issue. | None | Infection, leading to surgical intervention | |

Our records indicate that you may have received one or more of the affected products. The affected units were distributed between June 2021 and January 2022.



Hospital Responsibilities:

- 1. Review this Field Safety Notice and ensure that affected personnel are aware of the contents.
- 2. If you have affected product at your facility, assist your Zimmer Biomet sales representative and quarantine all affected product. Your Zimmer Biomet sales representative will remove the affected product from your facility.
- 3. If the product has been further distributed, provide your customers with the Field Safety Notice for hospitals and ensure documentation.
- 4. Complete **Attachment 1 Certificate of Acknowledgement** and send to <u>fieldaction.gscc@zimmerbiomet.com</u>. This form shall be returned even if you do not have affected products at your facility.
- 5. Retain a copy of the **Certificate of Acknowledgement** with your Field Safety Corrective Action records in the event of a compliance audit of your facility's documentation.
- 6. If you have further questions or concerns after reviewing this Field Safety Notice, please contact your local Zimmer Biomet representative.

Surgeon Responsibilities:

- 1. Review this Field Safety Notice for awareness of the contents.
- 2. There are no specific patient monitoring instructions related to this Field Safety Corrective Action that are recommended beyond your existing follow-up schedule.
- 3. Complete Attachment 1 Certificate of Acknowledgement and send to fieldaction.gscc@zimmerbiomet.com.
- 4. Retain a copy of the **Certificate of Acknowledgement** with your Field Safety Corrective Action records in the event of a compliance audit of your facility's documentation.
- 5. If you have further questions or concerns after reviewing this notice, please contact your local Zimmer Biomet representative.

Other Information

This medical device Field Safety Corrective Action was reported to all Competent Authorities and the related Notified Body as required under the applicable regulations for Medical Devices as per MEDDEV 2.12-1 in Europe.

Please keep Zimmer Biomet informed of any adverse events associated with this product or any other Zimmer Biomet product by emailing GSCC.Supplier.Quality@zimmerbiomet.com or your local Zimmer Biomet contact.

Please be aware that the names of user facilities notified are routinely provided to the Competent Authorities for audit purposes. The undersigned confirms that this Field Safety Notice has been delivered to the appropriate Regulatory Agencies.

We would like to thank you for your co-operation and regret any inconveniences caused by this Field Safety Corrective Action.

| Sincerely, | | | |
|------------|--|--|--|
| | | | |
| xxx | | | |



ATTACHMENT 1- Certificate of Acknowledgement IMMEDIATE RESPONSE REQUIRED - TIME SENSITIVE ACTION NEEDED

Affected Product: Upper Trauma, Lower Trauma, Foot & Ankle and Sports Medicine Field Safety Correction Action Reference: ZFA 2021-00263

Please return the <u>completed</u> form to your Zimmer Biomet contact person or by e-mail to: fieldaction.gscc@zimmerbiomet.com

| | | Rega | rding the parts: | | |
|--------|--|---|---|--|-----------------------|
| | ☐ A thorough search ha All products that ar | • | | nd the below are availabled or used: □ Yes | |
| Note | : All products that are not a | | be considered as disp nless otherwise specific | | nd therefore physical |
| | Item Number | Lot Number | UDI Num | ber Quantit | y Returned |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| · | v signing below, I acknowled | it to <u>fieldaction.gscc@</u> dge that I have receive | <u>zimmerbiomet.com</u> wit | h this form. d the contents of this Fi | |
| | [] Hospita | l Facility []S | Surgeon (Please ch | eck one as applicable) | |
| Printe | ed Name: | | Signature: | | |
| Title: | | Telep | hone: () | Date: | |
| Facili | ty Name: | | | | |
| Facili | ty Address: | | | | |
| City | | State | | 71D: | |

Note: This form will be returned to Zimmer Biomet before this action is closed for your account. It is important that you complete this form and email a copy to <u>fieldaction.gscc@zimmerbiomet.com</u>.

GBLT07107 Rev 1

Ref: GBLW07101 Global Field Action Activities



ATTACHMENT 2 - Affected Product List

| Item | Lot | Description | UDI Number |
|-----------|--------|--|--|
| Number | Number | Description | |
| 110010371 | 549910 | | (01)00887868465758(17)310603(10)549910 |
| 110010371 | 061400 | JuggerLoc Slotted Reamer, 6 MM | (01)00887868465758(17)310630(10)061400 |
| 110010371 | 061410 | Jugger Loc Slotted Neumer, 6 Wilvi | (01)00887868465758(17)310723(10)061410 |
| 110010371 | 089370 | | (01)00887868465758(17)310726(10)089370 |
| 110010372 | 886220 | | (01)00880304857285(17)310726(10)886220 |
| 110010372 | 886210 | | (01)00880304857285(17)310727(10)886210 |
| 110010372 | 886240 | | (01)00880304857285(17)310805(10)886240 |
| 110010372 | 886120 | | (01)00880304857285(17)310805(10)886120 |
| 110010372 | 886200 | | (01)00880304857285(17)310805(10)886200 |
| 110010372 | 886230 | | (01)00880304857285(17)310813(10)886230 |
| 110010372 | 886270 | | (01)00880304857285(17)310922(10)886270 |
| 110010372 | 886290 | | (01)00880304857285(17)310917(10)886290 |
| 110010372 | 886260 | JuggerLoc Slotted Reamer, 7 MM | (01)00880304857285(17)310922(10)886260 |
| 110010372 | 954760 | | (01)00880304857285(17)310922(10)954760 |
| 110010372 | 954740 | | (01)00880304857285(17)310922(10)954740 |
| 110010372 | 503610 | | (01)00880304857285(17)310924(10)503610 |
| 110010372 | 503410 | | (01)00880304857285(17)311011(10)503410 |
| 110010372 | 503430 | | (01)00880304857285(17)311011(10)503430 |
| 110010372 | 503460 | | (01)00880304857285(17)311011(10)503460 |
| 110010372 | 637200 | | (01)00880304857285(17)311027(10)637200 |
| 110010372 | 539370 | | (01)00880304857285(17)311105(10)539370 |
| 110010372 | 796600 | | (01)00880304857285(17)311105(10)796600 |
| 110010373 | 577860 | lugger of Slotted Beamer 9 MM | (01)00880304857292(17)310917(10)577860 |
| 110010373 | 577830 | JuggerLoc Slotted Reamer, 8 MM | (01)00880304857292(17)310917(10)577830 |
| 110010373 | 577840 | | (01)00880304857292(17)310922(10)577840 |
| 110018275 | 260770 | | (01)00880304857261(17)310917(10)260770 |
| 110018275 | 503420 | JuggerLoc Slotted Reamer, 5 MM | (01)00880304857261(17)310924(10)503420 |
| 110018275 | 503450 | | (01)00880304857261(17)310924(10)503450 |
| 110018275 | 796610 | | (01)00880304857261(17)311027(10)796610 |
| 131812126 | 101220 | DVR Crosslock Extra Long Plate, Right, 24 | (01)00887868446191(17)310623(10)101220 |
| 131812126 | 101560 | MM X 125 MM | (01)00887868446191(17)310624(10)101560 |
| 131812176 | 101340 | DVR Crosslock Extra Extra Long Plate, Right, 24 MM X 174 MM | (01)00887868446207(17)310625(10)101340 |
| 131822126 | 101450 | DVR Crosslock Extra Long Plate, Left, 24 MM X 125 MM | (01)00887868446313(17)310630(10)101450 |
| 131822126 | 119180 | | (01)00887868446313(17)310630(10)119180 |
| 131822126 | 154060 | V 152 IAIIAI | (01)00887868446313(17)310630(10)154060 |
| 212000022 | 119750 | | (01)00887868446054(17)310624(10)119750 |
| 212000022 | 119760 | DVR Drill Bit, 2.2 MM | (01)00887868446054(17)310624(10)119760 |
| 212000022 | 120800 | טעה טוווו סונ, 2.2 ועוועו | (01)00887868446054(17)310630(10)120800 |
| 212000022 | 120810 | | (01)00887868446054(17)310713(10)120810 |

GBLT07107 Rev 1

Ref: GBLW07101 Global Field Action Activities



| Item Number | Lot Number | Description | UDI Number |
|----------------|---------------|---|--|
| 212000022 | 331590 | | (01)00887868446054(17)310723(10)331590 |
| 212000022 | 331600 | | (01)00887868446054(17)310726(10)331600 |
| 212000022 | 391450 | | (01)00887868446054(17)310816(10)391450 |
| 212000022 | 416500 | | (01)00887868446054(17)310817(10)416500 |
| 212000022 | 416510 | DVR Drill Bit, 2.2 MM | (01)00887868446054(17)310817(10)416510 |
| 212000022 | 416520 | | (01)00887868446054(17)310819(10)416520 |
| 212000022 | 416640 | | (01)00887868446054(17)310823(10)416640 |
| 212000022 | 331580 | | (01)00887868446054(17)310803(10)331580 |
| 214227160 | 834950 | | (01)00887868446733(17)311101(10)834950 |
| 214227160 | 896640 | ALPS Calibrated Drill, 2.7 MM X 160 MM | (01)00887868446733(17)311101(10)896640 |
| 214227160 | 896660 | | (01)00887868446733(17)311027(10)896660 |
| 824150170 | 534680 | | (01)00887868446948(17)310713(10)534680 |
| 824150170 | 534690 | | (01)00887868446948(17)310713(10)534690 |
| 824150170 | 836360 | ALPS Cortical Tap, 3.5 MM X 140 MM | (01)00887868446948(17)310119(10)836360 |
| 824150170 | 534700 | | (01)00887868446948(17)310812(10)534700 |
| 824150170 | 610840 | | (01)00887868446948(17)310915(10)610840 |
| 824273100 | 386440 | ALPS Drill, 4.5 MM X 150 MM | (01)00887868447105(17)310809(10)386440 |
| 829029170 | 820340 | · | (01)00887868447006(17)310618(10)820340 |
| 829029170 | 084850 | | (01)00887868447006(17)310621(10)084850 |
| 829029170 | 084870 | | (01)00887868447006(17)310623(10)084870 |
| 829029170 | 084860 | | (01)00887868447006(17)310623(10)084860 |
| 829029170 | 084880 | | (01)00887868447006(17)310624(10)084880 |
| 829029170 | 102920 | | (01)00887868447006(17)310630(10)102920 |
| 829029170 | 205750 | ALDC D.:II 2 F MANA V 140 MANA | (01)00887868447006(17)310714(10)205750 |
| 829029170 | 204700 | ALPS Drill, 2.5 MM X 140 MM | (01)00887868447006(17)310714(10)204700 |
| 829029170 | 102930 | | (01)00887868447006(17)310716(10)102930 |
| 829029170 | 492660 | | (01)00887868447006(17)310722(10)492660 |
| 829029170 | 102960 | | (01)00887868447006(17)310728(10)102960 |
| 829029170 | 103120 | | (01)00887868447006(17)310728(10)103120 |
| 829029170 | 102940 | | (01)00887868447006(17)310729(10)102940 |
| 829029170 | 102950 | | (01)00887868447006(17)310729(10)102950 |
| 829032170 | 014490 | ALPS Drill, 3.5 MM X 140 MM | (01)00887868447037(17)310608(10)014490 |
| 829516150 | 939270 | | (01)00887868447068(17)310601(10)939270 |
| 829516150 | 964360 | | (01)00887868447068(17)310603(10)964360 |
| 829516150 | 014500 | ALPS Bayonet Tip Guide Pin, 1.6 MM X 150 | (01)00887868447068(17)310608(10)014500 |
| 829516150 | 014520 | MM | (01)00887868447068(17)310610(10)014520 |
| 829516150 | 391660 | | (01)00887868447068(17)310811(10)391660 |
| 829516150 | 391470 | | (01)00887868447068(17)310811(10)391470 |
| 829516151 | 806490 | ALPS Threaded Tip Guide Pin, 1.6 MM X 150 | (01)00887868447075(17)310528(10)806490 |
| 829516151 | 391670 | MM | (01)00887868447075(17)310811(10)391670 |
| 856204008 | 913430 | ALPS Fibula Composite Locking Plate, 8 Hole | (01)00887868445897(17)310616(10)913430 |