



REHATEC GmbH | In den Kreuzwiesen 35 | 69250 Schönau

Schönau, 24 April 2021

## **Urgent Field Safety Notice**

Type of action: Replacement of motor drives

Products: Lasse size 3, Lasse size 4, Da Vinci size 1, Da Vinci size 2

Dear Sir or Madam,

The number one priority of Rehatec GmbH is the continued safety of our customers. Unfortunately, we have identified that some of the products listed above may potentially show an assembly error affecting the motor drive caused by the manufacturer.

To ensure and maintain the safety of our customers, we are bound to replace all motor drives affected based on their serial number. Please complete the attached "customer reply form" and send it back to us as soon as possible.

We are sorry for any inconvenience this may have caused. Thank you for your support.

Best regards

Rehatec GmbH