<FINAL TEMPLATE> <Modify country specific contact information>



URGENT FIELD SAFETY NOTICE/ DEVICE RECALL

COMMERCIAL NAME: StarClose SE Vascular Closure System FS CA-Identifier: February 10, 2017 Type of Action: Device Recall

Attention: Risk Manager or Health Care Professional

Dear Valued Abbott Vascular Customer:

Abbott Vascular has initiated a voluntary field action regarding specific lots of the StarClose SE Vascular Closure System. Our records indicate that affected lots have been shipped to your account.

Product from the identified lots may exhibit difficulty or failure to deploy the StarClose SE Clip. Potential risks associated with this event include prolonged procedure times, use of another device or manual compression to achieve hemostasis. There have been no long term or irreversible patient effects reported.

This action does not affect patients having successfully undergone cardiac or endovascular procedures using the StarClose SE Vascular Closure System.

How does this issue occur?:

Exchange sheath material variation with a higher sheath split force may result in difficulty or failure to deploy the device.

What action is Abbott Vascular asking you to take?:

- Please reference the attached list of affected part numbers and lot numbers
- The use of devices from these lots should cease immediately
- Please review your inventory, complete the attached Effectiveness Check Form
- Return all unused identified products to Abbott Vascular
- Share this notification with other relevant personnel in your organization

What is Abbott Vascular doing?:

Abbott Vascular has already implemented corrective actions to ensure ongoing product performance and has ceased distributing any product built before the corrective actions. Abbott Vascular will work with you to replace returned units with similar product, pending availability. The appropriate regulatory agencies have been notified of this action.

We regret any inconvenience this may cause you and appreciate your patience. Abbott Vascular is committed to providing high quality products and ensuring customer satisfaction. If you have any questions, please do not hesitate to contact your local Abbott Vascular Representative or Customer Service department on xxxx xxxxxx.

Sincerely,

[Name] GM / Country Manager



URGENT FIELD SAFETY NOTICE / DEVICE RECALL February 10, 2017

| Green Sheath (Part Number 14679-02) 50831K1 50903K1 50908K1 50911K1 50921K1 50924K1 50929K1 50929K1 51002K1 51002K1 51002K1 51002K1 51002K1 51002K1 51010K1 51029K1 51029K1 51029K1 51029K1 51029K1 51103K1 5112041 5112041 5112041 5112041 5120141 5120141 6011641 601141 601141 6011941 6011941 6031041 6031541 6032241 6032241 6042941 6042941 6051341 6051341 6051941 6051941 6051941 | StarClose SE VCS, International |
|--|---------------------------------|
| (Part Number 14679-02) 50831K1 50903K1 50908K1 50911K1 50921K1 50924K1 50929K1 51002K1 51002K1 51002K1 51002K1 51002K1 51002K1 51016K1 510298K1 510298K1 51029K1 51029K1 51029K1 51029K1 5112041 5112041 5112041 5112041 5120141 512041 6010641 601141 6011941 6011941 6031041 6031041 6032241 6032241 6032941 6042941 6042941 6051341 6051341 6051941 6051941 6051941 | |
| 50831K1 50903K1 50908K1 50911K1 50921K1 50924K1 50929K1 51002K1 51008K1 51008K1 51026K1 51026K1 51026K1 51028K1 51028K1 51026K1 510241 51103K1 511241 511241 5112041 5112041 5112041 5112041 6010641 601141 6011441 6011441 6011441 6031041 6031041 6031041 6032241 6032941 6041941 6042641 6042941 6051341 6051341 6051941 6051941 6051541 | |
| 50903K1 50908K1 50911K1 50921K1 50924K1 50929K1 51002K1 51008K1 51008K1 51016K1 51029K1 51029K1 51029K1 51029K1 51103K1 5110241 5112041 5112741 512041 512041 512041 6010641 601141 6011441 6011441 6031041 6031041 6031041 6032241 6032941 6041941 6042941 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 | |
| 50908K1 50911K1 50921K1 50924K1 50929K1 51002K1 51008K1 51026K1 51026K1 51028K1 51028K1 51029K1 51103K1 5110241 5112041 5112041 5112041 5112041 512041 512041 512041 512041 6010641 6011441 6011941 6011941 6031041 6031541 6032241 6032941 6041941 6042941 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 6051341 | |
| 50911K1 50921K1 50924K1 50929K1 51002K1 51008K1 51016K1 51026K1 51029K1 51029K1 51029K1 51103K1 5110241 5112041 5112041 5112041 5112041 5112041 5120441 6010641 601141 601141 6011941 6012241 6031041 6032241 6032941 6042941 6042941 6051341 6051341 6051341 6051341 6051341 | |
| 50921K1 50929K1 51002K1 51002K1 51008K1 51016K1 51026K1 51029K1 51103K1 511241 5112041 5112041 511241 5112441 512041 512041 512041 512041 6010641 601141 601141 6011941 6031041 6031041 6032241 6032941 6042141 6042641 6051341 6051341 6051341 6051341 6051341 | |
| 50924K1 50929K1 51002K1 51008K1 51016K1 51026K1 51029K1 51029K1 51103K1 51103K1 5112041 5112041 511241 5120141 5120141 5120441 6010641 6011141 6011441 6011941 6012241 6031041 6031541 6032241 6032241 6042141 6042141 6042141 6051341 6051341 6051341 6051341 6051341 6051341 | |
| 50929K1 51002K1 51008K1 51016K1 51026K1 51029K1 51103K1 511241 511241 5120141 512041 512041 512041 512041 512041 512041 6010641 6010641 601141 601141 6012241 6031041 6031541 6032241 6032241 6032241 6032941 6042141 6042141 6051341 6051341 6051341 6051341 6051941 6051941 | |
| 51002K1 51008K1 51016K1 51026K1 51029K1 51103K1 5111741 5112041 5112041 5112741 5120141 5120141 512041 6010641 6011441 6011941 6012241 6031041 6031541 6032241 6032241 6032241 6032241 6032241 6031541 6042941 6042141 6051341 6051341 6051341 6051941 6051941 | |
| 51008K1 51016K1 51026K1 51029K1 51103K1 5111741 5112041 5112741 5120141 5120141 6010641 6011441 6011941 6012241 6031041 6032241 6032241 6032241 6032941 6042941 6051341 6051341 6051341 6051941 6051941 6051941 | |
| 51016K1 51026K1 51029K1 51103K1 5111741 5112041 5112441 5112741 5120141 5120141 6010641 6011441 6011441 6011941 6012241 6031041 6031541 6032241 6032241 6032941 6042641 6042641 6051341 6051341 6051941 6051941 6051941 | |
| 51026K1 51029K1 51103K1 5111741 5112041 5112441 5112441 5120141 5120441 6010641 6011441 6011941 6012241 6031041 6031541 6032241 6032241 6032941 6042941 6042641 6051341 6051341 6051941 6051941 6051941 | |
| 51029K1 51103K1 5111741 5112041 5112441 5112741 5120141 5120441 6010641 6011441 6011941 6012241 6031041 6032241 6032241 6032241 6032241 6032241 6032241 6032241 6032241 6032241 6032241 6031541 6032941 6042941 6042641 6051341 6051341 6051341 6051941 6051941 | |
| 51103K1 5111741 5112041 5112441 5112741 5120141 5120141 6010641 6011441 6011941 6012241 6031041 6031541 6032241 6032241 6032241 6032241 6032241 6032241 6032941 6042941 6042641 6051341 6051341 6051941 6051941 6051941 | |
| $\begin{array}{c} 5111741 \\ 5112041 \\ 5112441 \\ 5112741 \\ 5120141 \\ 5120141 \\ 6010641 \\ 6010641 \\ 6011441 \\ 6011441 \\ 6011941 \\ 6012241 \\ 6031041 \\ 6031041 \\ 6032241 \\ 6032241 \\ 6032941 \\ 6032941 \\ 6042941 \\ 6042641 \\ 6042941 \\ 6051341 \\ 6051341 \\ 6051941 \\ 6051941 \\ 6051941 \\ 6052441 \\ 6051941 \\$ | |
| $\begin{array}{c} 5112041 \\ 5112441 \\ 5112741 \\ 5120141 \\ 5120141 \\ 6010641 \\ 6010641 \\ 6011441 \\ 6011441 \\ 6011941 \\ 6012241 \\ 6031041 \\ 6031541 \\ 6032241 \\ 6032241 \\ 6032941 \\ 6032941 \\ 6042941 \\ 6042641 \\ 6042941 \\ 6051341 \\ 6051341 \\ 6051941 \\ 6051941 \\ 6051941 \\ 6051941 \\ 6051941 \\ 6061541 \end{array}$ | |
| $\begin{array}{c} 5112441 \\ 5112741 \\ 5120141 \\ 5120141 \\ 6010641 \\ 6010641 \\ 6011441 \\ 6011941 \\ 6012241 \\ 6031041 \\ 6031041 \\ 6031541 \\ 6032241 \\ 6032241 \\ 6032241 \\ 6032941 \\ 6042941 \\ 6042641 \\ 6042641 \\ 6042941 \\ 6051341 \\ 6051341 \\ 6051941 \\ 6051941 \\ 6051941 \\ 6051941 \\ 6061541 \end{array}$ | |
| $\begin{array}{r} 5112741 \\ 5120141 \\ 5120441 \\ 6010641 \\ 6010641 \\ 6011441 \\ 6011941 \\ 6012241 \\ 6031041 \\ 6031541 \\ 6032241 \\ 6032241 \\ 6032241 \\ 6032941 \\ 6042941 \\ 6042641 \\ 6042641 \\ 6042941 \\ 6051341 \\ 6051341 \\ 6051941 \\ 6051941 \\ 6051941 \\ 6061541 \end{array}$ | |
| $\begin{array}{r} 5120441 \\ 6010641 \\ 6011141 \\ 6011141 \\ 6011441 \\ 6011941 \\ 6012241 \\ 6031041 \\ 6031541 \\ 6032241 \\ 6032241 \\ 6032941 \\ 6032941 \\ 6041941 \\ 6042141 \\ 6042641 \\ 6042941 \\ 6051341 \\ 6051341 \\ 6051941 \\ 6051941 \\ 6051941 \\ 6051541 \end{array}$ | |
| 6010641 6011141 6011441 6011941 6012241 6031041 6031541 6032241 6032941 6041941 6042641 6051141 6051341 6051941 6051941 6051541 | 5120141 |
| $\begin{array}{c} 6011141 \\ 6011441 \\ 6011941 \\ 6012241 \\ 6031041 \\ 6031541 \\ 6032241 \\ 6032241 \\ 6032941 \\ 6042941 \\ 6042641 \\ 6042641 \\ 6042941 \\ 6051341 \\ 6051341 \\ 6051941 \\ 6052441 \\ 6051941 \\ 6051541 \end{array}$ | 5120441 |
| 6011441 6011941 6012241 6031041 6031541 6032241 6032941 6042941 6042641 6051341 6051941 6051941 6051941 6051541 | 6010641 |
| 6011941 6012241 6031041 6031541 6032241 6032941 6041941 6042641 6051141 6051341 6051941 6051941 6051541 | 6011141 |
| 6012241 6031041 6031541 6032241 6032941 6041941 6042141 6042641 6051141 6051341 6051941 6051941 6051541 | 6011441 |
| 6031041 6031541 6032241 6032941 6041941 6042141 6042641 6042941 6051141 6051341 6052441 6051941 6051541 | 6011941 |
| 6031541 6032241 6032941 6041941 6042141 6042641 6042941 6051141 6051341 6051941 6052441 6051941 6051541 | 6012241 |
| 6032241 6032941 6041941 6042141 6042641 6042941 6051141 6051341 6051941 6052441 6051541 | 6031041 |
| 6032941 6041941 6042141 6042641 6042941 6051141 6051341 6051941 6052441 6061541 | 6031541 |
| 6041941 6042141 6042641 6042941 6051141 6051341 6051941 6052441 6061541 | 6032241 |
| 6042141 6042641 6042941 6051141 6051341 6051941 6052441 6061541 | 6032941 |
| 6042641 6042941 6051141 6051341 6051941 6052441 6061541 | 6041941 |
| 6042941 6051141 6051341 6051941 6052441 6061541 | 6042141 |
| 6051141 6051341 6051941 6052441 6061541 | 6042641 |
| 6051341 6051941 6052441 6061541 | 6042941 |
| 6051941 6052441 6061541 | 6051141 |
| 6052441 6061541 | |
| 6061541 | 6051941 |
| | 6052441 |
| 6100241 | |
| 0100341 | 6100341 |



<Modify country specific contact information>

URGENT FIELD SAFETY NOTICE/ DEVICE RECALL

COMMERCIAL NAME: StarClose SE Vascular Closure System FS CA-Identifier: February 10, 2017 Type of Action: Device Recall

Effectiveness Check Form

| Customer Account # | ŧ | |
|--------------------|---|--|
| Account Name | | |
| Address | | |
| | | |

(Information required for regulatory effectiveness check)

After reviewing your inventory of StarClose SE Vascular Closure System, please check one box in the section below. If affected inventory was identified, please contact Customer Services to obtain a Returned Goods Authorization (RGA) number. After signing this form, please return the form and any identified products to Abbott Vascular.

| A thorough search for all affected products has been completed and no affected units remain in inventory. No devices will be returned. |
|---|
| Affected StarClose SE Vascular Closure Systems have been identified and are being returned. |
| RGA Number: |

Customer Name/ Title (print)

Signature

Date

This form is to be returned to Abbott Vascular

- □ If returning product, call Abbott Vascular Customer Service XXX XXX XXXX to receive RGA number. Record RGA number above.
- □ Fax this completed form to XXX XXX XXXX or scan an e-mail to XXXXXXXXXXXXXXX
- □ Return a copy of this completed form with the returned product.

