

«Nom_de_lEtablissement_» «Nom_du_correspondant»

«Adresse_1» «Adresse_2» «CP_VILLE_»

Quality contact:

₽

Mail ref: 17 0366 «N_de_Chrono»CO/NU

Ecouen, 19th July, 2017

Subject: URGENT: FSN-RECALL

UMBILICAL CATHETER code 270.03

Dear Madam, Sir,

We have identified a non-systematic wrong marking on our devices umbilical catheter code 270.03

lots 241116FR - 281116FR - 071216FR - 151216FR - 211216FR - 050117FR - 060117FR - 150217FR - 230217FR and 280217FR

the first marking from the distal tip may be at 5,5 cm instead of 4 cm.

For safety reasons, we ask you to withdraw these batches immediately.

We ask you to kindly acknowledge receipt of this letter, to complete and return the attached form by indicating the quantities involved withdrawn from your institution.

The French health authorities (ANSM) have been informed of this FSN.

For further information, you can directly contact M. xxxxxxxx, quality contact, or sales administration phone number xxxxxxxxxxx.

We apologize for any inconvenience this FSN-Recall may cause.

.....

Service Qualité Tél: 01.39.92.63.51 Fax: 01.39.92.64.82 E-mail: quality@vygon.com Service Clients France
Tél: 01.39.92.63.81
Fax: 01.39.90.29.37
E-mail: commandes@vygon.com

Service Clients Export Tél: 01.39.92.64.17 Fax: 01.34.29.19.34 E-mail: export@vygon.com







URGENT: FSN-RECALL UMBILICAL CATHETER code 270.03 ACKNOWLEDGMENT AND CUSTOMER RESPONSE FORM

Please complete and return this form by fax: xxxxxxxxxx or e-mail to : xxxxxxxxxxx

Name and address of the institution :	
Full name of the person to contact:	«N_de_Chrono»CO/NU »
	« TOWN »
Function:	
Phone number :	
Thone name :	
ூ் E-mail :	
We acknowledge receipt of the above FSN and that the information contained in this field safety notice has	
been shared with all recipients/ end users of product listed below within your organization.	
Please tick the appropriate box: You have UMBILICAL CATHETER code 270.03	
Let 24444CFD. DVec D No. If you have write number of write newsons.	
Lot 241116FR: ☐Yes ☐ No If you have units, number of units removed:	
Lot 281116FR: ☐Yes ☐ No If you have units, number of units removed:	
Lot 071216FR: □Yes □ No If you have units, number of units removed:	
Lot 151216FR: ☐Yes ☐ No If you have units, number of units removed:	
Lot 211216FR: ☐Yes ☐ No If you have units, number of units removed:	
Lot 050117FR: ☐Yes ☐ No If you have units, number of units removed:	
Est osori/M. Tres The myou have units, number of units removed.	
Lot 060117FR : □Yes □ No If you have units,	number of units removed:
Lot 150217FR: ☐Yes ☐ No If you have units, number of units removed:	
Lot 230217FR: □Yes □ No If you have units, number of units removed:	
Lot 250217FR. Tes Til No Til you have units, number of units removed:	
Lot 280217FR: ☐Yes ☐ No If you have units, number of units removed:	
Signature and Date:	

Service Qualité Tél : 01.39.92.63.51 Fax : 01.39.92.64.82 E-mail : quality@vygon.com Service Clients France Tél : 01.39.92.63.81 Fax : 01.39.90.29.37 E-mail : commandes@vygon.com Service Clients Export Tél : 01.39.92.64.17 Fax : 01.34.29.19.34 E-mail : export@vygon.com



